



ELBOARD/PANNEAU/TABLERO

CHB

77/480 Fed From

~~DISC~~ ~~CR~~ ~~DP~~ CBD

SOURCE	LOAD / CHARGE / CARGA	CIR	LOAD / CHARGE / CARGA
SPARE		2	SPARE
SPARE		4	SPARE
SPARE		6	SPARE
Lights Central Sec B		8	Lighting Westside Sec B
Lights East Sec B		10	Lighting Westside Sec B
Lights East Sec B		12	Lighting Southwest Sec A.
Lights Sec C Patient Recov		14	Lights Sec C Pathology LAB
Lights Sec C South - SW		16	Lights Sec C North Northwest
Lights Sec C Operating Rm		18	SPARE
Lights NW, SW, NE Court.		20	Roadside Sign
		22	Roadside Sign
		24	SPARE
		26	
		28	SPACE
		30	
		32	
		34	
		36	
		38	
		40	
		42	
		44	
		46	
		48	
		50	
		52	

SPACE
↑
↓

SPACE
↑
↓

3 OFF

5 20A EXPLOSION

7

9

11 20A EXPLOSION

13

15 20A EXPLOSION

17

19 20A EXPLOSION

21

23

25

27

29

⚠ DANGER
 HAZARD OF ELECTRIC SHOCK, BURN OR EXPLOSION
 • Before energizing panel-board, all unused spaces must be filled with blank fillers.
 Failure to follow this instruction will result in death or serious injury.

⚠ DANGER
 RISQUE D'ELECTROCUTION, DE BRULURES OU D'EXPLOSION
 • Avant de mettre le panneau sous tension, tous les emplacements inutilisés doivent être couverts avec des plaquettes.
 Si cette précaution n'est pas respectée, cela entraînera la mort ou des blessures graves.

⚠ PELIGRO
 PELIGRO DE DESCARGA ELECTRICA, QUEMADURAS O EXPLOSION
 • Antes de energizar el tablero, todos los espacios sin usar deben ser cubiertos con placas de relleno.
 El incumplimiento de esta precaución podrá causar la muerte o lesiones serias.

80013-302-01

4 20A EXPLOSION

6 OFF

8

10

12 20A EXPLOSION

14

16

18 OFF

20 20A EXPLOSION

22 20A EXPLOSION

24 OFF

26

28

30